

OE NO. 48530-52730 Rear Shock Absorbers for TOYOTA VITZ Perfect Fit and Performance

Our Product Introduction

Basic Information

- Place of Origin: Guangdong, China
- Brand Name: MASUMA
- Minimum Order Quantity: 2 pieces
- Price: Negotiation
- Packaging Details: carton
- Supply Ability: 100000 Piece/Pieces per Week

MASUMA
 AUTO SPARE PARTS



Product Specification

- Model: ECHO Saloon (_P1_), YARIS (_P1_)
- Year: 1999-2006, 1999-2005, 1999-2005
- OE NO.: 48530-0D140, 48530-09820, 48530-0D040, 48530-52072, 48530-52231, 48530-52360, 48530-52400, 48530-52660, 48530-52730, 48530-52750, 48530-59176, 48530-59177, 48530-59196, 48530-59326, 48530-59327, 48530-59445, 48530-59446, 48530-59675, 48530-59785, 48530-802
- Car Fitment: Toyota
- Reference NO.: MJ20070, J5522002G, MA20070, A1236G, MM20070, 1236G, 63451236, 230 505, DSF097G, 280523-PCS-MS, 81-1522, DS1007GT, 20343090, 30-26 725 0001, DG 8059, 179574, BNE-6856, DG8059, JGT255T, 3212-0037-SX
- Warranty: 12 Months, Warranty 12 Months Or 30 Thousand Kilometer
- Car Model: JAPAN

MASUMA	Brand	Car model	Chassis number	Year	Configuration
P5452	TOYOTA	ECHO	HCPI2	1999-2000	HCPI2 1900L 2000
P5452	TOYOTA	PLATZ	HCPI2	2000-2001	HCPI2 1900L 2000
P5452	TOYOTA	PLATZ	HCPI2	2001-2002	HCPI2 1900L 2000
P5452	TOYOTA	PLATZ	HCPI2	2002-2003	HCPI2 1900L 2000
P5452	TOYOTA	PLATZ	HCPI2	2003-2004	HCPI2 1900L 2000
P5452	TOYOTA	PLATZ	HCPI2	2004-2005	HCPI2 1900L 2000
P5452	TOYOTA	PLATZ	HCPI2	2005-2006	HCPI2 1900L 2000
P5452	TOYOTA	PLATZ	HCPI2	2006-2007	HCPI2 1900L 2000
P5452	TOYOTA	PLATZ	HCPI2	2007-2008	HCPI2 1900L 2000
P5452	TOYOTA	PLATZ	HCPI2	2008-2009	HCPI2 1900L 2000
P5452	TOYOTA	PLATZ	HCPI2	2009-2010	HCPI2 1900L 2000
P5452	TOYOTA	PLATZ	HCPI2	2010-2011	HCPI2 1900L 2000
P5452	TOYOTA	PLATZ	HCPI2	2011-2012	HCPI2 1900L 2000
P5452	TOYOTA	PLATZ	HCPI2	2012-2013	HCPI2 1900L 2000
P5452	TOYOTA	PLATZ	HCPI2	2013-2014	HCPI2 1900L 2000
P5452	TOYOTA	PLATZ	HCPI2	2014-2015	HCPI2 1900L 2000
P5452	TOYOTA	PLATZ	HCPI2	2015-2016	HCPI2 1900L 2000
P5452	TOYOTA	PLATZ	HCPI2	2016-2017	HCPI2 1900L 2000
P5452	TOYOTA	PLATZ	HCPI2	2017-2018	HCPI2 1900L 2000
P5452	TOYOTA	PLATZ	HCPI2	2018-2019	HCPI2 1900L 2000
P5452	TOYOTA	PLATZ	HCPI2	2019-2020	HCPI2 1900L 2000
P5452	TOYOTA	PLATZ	HCPI2	2020-2021	HCPI2 1900L 2000
P5452	TOYOTA	PLATZ	HCPI2	2021-2022	HCPI2 1900L 2000
P5452	TOYOTA	PLATZ	HCPI2	2022-2023	HCPI2 1900L 2000
P5452	TOYOTA	PLATZ	HCPI2	2023-2024	HCPI2 1900L 2000
P5452	TOYOTA	PLATZ	HCPI2	2024-2025	HCPI2 1900L 2000
P5452	TOYOTA	PLATZ	HCPI2	2025-2026	HCPI2 1900L 2000
P5452	TOYOTA	PLATZ	HCPI2	2026-2027	HCPI2 1900L 2000
P5452	TOYOTA	PLATZ	HCPI2	2027-2028	HCPI2 1900L 2000
P5452	TOYOTA	PLATZ	HCPI2	2028-2029	HCPI2 1900L 2000
P5452	TOYOTA	PLATZ	HCPI2	2029-2030	HCPI2 1900L 2000
P5452	TOYOTA	PLATZ	HCPI2	2030-2031	HCPI2 1900L 2000
P5452	TOYOTA	PLATZ	HCPI2	2031-2032	HCPI2 1900L 2000
P5452	TOYOTA	PLATZ	HCPI2	2032-2033	HCPI2 1900L 2000
P5452	TOYOTA	PLATZ	HCPI2	2033-2034	HCPI2 1900L 2000
P5452	TOYOTA	PLATZ	HCPI2	2034-2035	HCPI2 1900L 2000
P5452	TOYOTA	PLATZ	HCPI2	2035-2036	HCPI2 1900L 2000
P5452	TOYOTA	PLATZ	HCPI2	2036-2037	HCPI2 1900L 2000
P5452	TOYOTA	PLATZ	HCPI2	2037-2038	HCPI2 1900L 2000
P5452	TOYOTA	PLATZ	HCPI2	2038-2039	HCPI2 1900L 2000
P5452	TOYOTA	PLATZ	HCPI2	2039-2040	HCPI2 1900L 2000
P5452	TOYOTA	PLATZ	HCPI2	2040-2041	HCPI2 1900L 2000
P5452	TOYOTA	PLATZ	HCPI2	2041-2042	HCPI2 1900L 2000
P5452	TOYOTA	PLATZ	HCPI2	2042-2043	HCPI2 1900L 2000
P5452	TOYOTA	PLATZ	HCPI2	2043-2044	HCPI2 1900L 2000
P5452	TOYOTA	PLATZ	HCPI2	2044-2045	HCPI2 1900L 2000
P5452	TOYOTA	PLATZ	HCPI2	2045-2046	HCPI2 1900L 2000
P5452	TOYOTA	PLATZ	HCPI2	2046-2047	HCPI2 1900L 2000
P5452	TOYOTA	PLATZ	HCPI2	2047-2048	HCPI2 1900L 2000
P5452	TOYOTA	PLATZ	HCPI2	2048-2049	HCPI2 1900L 2000
P5452	TOYOTA	PLATZ	HCPI2	2049-2050	HCPI2 1900L 2000
P5452	TOYOTA	PLATZ	HCPI2	2050-2051	HCPI2 1900L 2000
P5452	TOYOTA	PLATZ	HCPI2	2051-2052	HCPI2 1900L 2000
P5452	TOYOTA	PLATZ	HCPI2	2052-2053	HCPI2 1900L 2000
P5452	TOYOTA	PLATZ	HCPI2	2053-2054	HCPI2 1900L 2000
P5452	TOYOTA	PLATZ	HCPI2	2054-2055	HCPI2 1900L 2000
P5452	TOYOTA	PLATZ	HCPI2	2055-2056	HCPI2 1900L 2000
P5452	TOYOTA	PLATZ	HCPI2	2056-2057	HCPI2 1900L 2000
P5452	TOYOTA	PLATZ	HCPI2	2057-2058	HCPI2 1900L 2000
P5452	TOYOTA	PLATZ	HCPI2	2058-2059	HCPI2 1900L 2000
P5452	TOYOTA	PLATZ	HCPI2	2059-2060	HCPI2 1900L 2000
P5452	TOYOTA	PLATZ	HCPI2	2060-2061	HCPI2 1900L 2000
P5452	TOYOTA	PLATZ	HCPI2	2061-2062	HCPI2 1900L 2000
P5452	TOYOTA	PLATZ	HCPI2	2062-2063	HCPI2 1900L 2000
P5452	TOYOTA	PLATZ	HCPI2	2063-2064	HCPI2 1900L 2000
P5452	TOYOTA	PLATZ	HCPI2	2064-2065	HCPI2 1900L 2000
P5452	TOYOTA	PLATZ	HCPI2	2065-2066	HCPI2 1900L 2000
P5452	TOYOTA	PLATZ	HCPI2	2066-2067	HCPI2 1900L 2000
P5452	TOYOTA	PLATZ	HCPI2	2067-2068	HCPI2 1900L 2000
P5452	TOYOTA	PLATZ	HCPI2	2068-2069	HCPI2 1900L 2000
P5452	TOYOTA	PLATZ	HCPI2	2069-2070	HCPI2 1900L 2000
P5452	TOYOTA	PLATZ	HCPI2	2070-2071	HCPI2 1900L 2000
P5452	TOYOTA	PLATZ	HCPI2	2071-2072	HCPI2 1900L 2000
P5452	TOYOTA	PLATZ	HCPI2	2072-2073	HCPI2 1900L 2000
P5452	TOYOTA	PLATZ	HCPI2	2073-2074	HCPI2 1900L 2000
P5452	TOYOTA	PLATZ	HCPI2	2074-2075	HCPI2 1900L 2000
P5452	TOYOTA	PLATZ	HCPI2	2075-2076	HCPI2 1900L 2000
P5452	TOYOTA	PLATZ	HCPI2	2076-2077	HCPI2 1900L 2000
P5452	TOYOTA	PLATZ	HCPI2	2077-2078	HCPI2 1900L 2000
P5452	TOYOTA	PLATZ	HCPI2	2078-2079	HCPI2 1900L 2000
P5452	TOYOTA	PLATZ	HCPI2	2079-2080	HCPI2 1900L 2000
P5452	TOYOTA	PLATZ	HCPI2	2080-2081	HCPI2 1900L 2000
P5452	TOYOTA	PLATZ	HCPI2	2081-2082	HCPI2 1900L 2000
P5452	TOYOTA	PLATZ	HCPI2	2082-2083	HCPI2 1900L 2000
P5452	TOYOTA	PLATZ	HCPI2	2083-2084	HCPI2 1900L 2000
P5452	TOYOTA	PLATZ	HCPI2	2084-2085	HCPI2 1900L 2000
P5452	TOYOTA	PLATZ	HCPI2	2085-2086	HCPI2 1900L 2000
P5452	TOYOTA	PLATZ	HCPI2	2086-2087	HCPI2 1900L 2000
P5452	TOYOTA	PLATZ	HCPI2	2087-2088	HCPI2 1900L 2000
P5452	TOYOTA	PLATZ	HCPI2	2088-2089	HCPI2 1900L 2000
P5452	TOYOTA	PLATZ	HCPI2	2089-2090	HCPI2 1900L 2000
P5452	TOYOTA	PLATZ	HCPI2	2090-2091	HCPI2 1900L 2000
P5452	TOYOTA	PLATZ	HCPI2	2091-2092	HCPI2 1900L 2000
P5452	TOYOTA	PLATZ	HCPI2	2092-2093	HCPI2 1900L 2000
P5452	TOYOTA	PLATZ	HCPI2	2093-2094	HCPI2 1900L 2000
P5452	TOYOTA	PLATZ	HCPI2	2094-2095	HCPI2 1900L 2000
P5452	TOYOTA	PLATZ	HCPI2	2095-2096	HCPI2 1900L 2000
P5452	TOYOTA	PLATZ	HCPI2	2096-2097	HCPI2 1900L 2000
P5452	TOYOTA	PLATZ	HCPI2	2097-2098	HCPI2 1900L 2000
P5452	TOYOTA	PLATZ	HCPI2	2098-2099	HCPI2 1900L 2000
P5452	TOYOTA	PLATZ	HCPI2	2099-2100	HCPI2 1900L 2000

Contact Supplier send an enquiry to
confirm suitable car

More Images



for more products please visit us on masumajp.com

Product Description



Product Description

MASUMA No.	P5452
Part Name	Suspension shock absorber
OEM No.	48530-0D140
Maintenance	Warranty 12 months or 30 thousand kilometer
In stock	In stock

Masuma shocks are manufactured to original OEM specifications. Masuma struts and shock absorbers are not tuning, but a quality replacement for original parts with additional improvements. The stems of Masuma shock absorbers have micro-notches that help lubricate the stem packing. This extends the life of the oil seal and the entire shock absorber. Shock absorbers are guaranteed for 12 months. Wherever you bought or installed a part, within a year you have the right to return it by simply providing him with a receipt or other document confirming the purchase date and price. Even if you are not a certified auto mechanic and installed the part yourself in your garage, just keep your purchase receipt and, if a problem arises, you can always return the part. Masuma is a global brand of auto parts, components and consumables. The main specialization of the brand: resource parts for post-warranty service of Japanese cars. The company's strategy is to offer consumers the best ratio of reliability and cost of spare parts.


SUITABLE FOR CAR MODELS DETAILS

MASUMA	Brand	Car model	Chassis number	Year	Configuration
P5452	TOYOTA	YARIS	NLP10L	2001-2002	NLP10L 1400 1NDTV SOHC INTERCOOLER TURBO. HATCHBACK 2WD Door 3
P5452	TOYOTA	YARIS	NLP10L	2001-2002	NLP10L 1400 1NDTV SOHC INTERCOOLER TURBO. HATCHBACK 2WD Door 5
P5452	TOYOTA	YARIS	NLP10L	2002-2003	NLP10L 1400 1NDTV SOHC INTERCOOLER TURBO. HATCHBACK 2WD Door 3
P5452	TOYOTA	YARIS	NLP10L	2002-2003	NLP10L 1400 1NDTV SOHC INTERCOOLER TURBO. HATCHBACK 2WD Door 5
P5452	TOYOTA	YARIS	NLP10L	2003-2005	NLP10L 1400 1NDTV SOHC INTERCOOLER TURBO. HATCHBACK 2WD Door 3
P5452	TOYOTA	YARIS	NLP10L	2003-2005	NLP10L 1400 1NDTV SOHC INTERCOOLER TURBO. HATCHBACK 2WD Door 5
P5452	TOYOTA	YARIS	NCP10L	1999-2000	NCP10L 1300 2NZFE DOHC EFI HATCHBACK 2WD Door 3
P5452	TOYOTA	YARIS	NCP10L	1999-2000	NCP10L 1300 2NZFE DOHC EFI HATCHBACK 2WD Door 5
P5452	TOYOTA	YARIS	NCP10L	2000-2002	NCP10L 1300 2NZFE DOHC EFI HATCHBACK 2WD Door 3
P5452	TOYOTA	YARIS	NCP10L	2000-2002	NCP10L 1300 2NZFE DOHC EFI HATCHBACK 2WD Door 5
P5452	TOYOTA	YARIS	SCP10L	1999-1999	SCP10L 1000 1SZFE DOHC EFI HATCHBACK 2WD Door 3
P5452	TOYOTA	YARIS	SCP10L	1999-1999	SCP10L 1000 1SZFE DOHC EFI HATCHBACK 2WD Door 5
P5452	TOYOTA	YARIS	SCP10L	1999-2000	SCP10L 1000 1SZFE DOHC EFI HATCHBACK 2WD Door 3
P5452	TOYOTA	YARIS	SCP10L	1999-2000	SCP10L 1000 1SZFE DOHC EFI HATCHBACK 2WD Door 5
P5452	TOYOTA	YARIS	SCP10L	2000-2002	SCP10L 1000 1SZFE DOHC EFI HATCHBACK 2WD Door 3
P5452	TOYOTA	YARIS	SCP10L	2000-2002	SCP10L 1000 1SZFE DOHC EFI HATCHBACK 2WD Door 5
P5452	TOYOTA	YARIS	SCP10L	2001-2002	SCP10L 1000 1SZFE DOHC EFI HATCHBACK 2WD Door 3
P5452	TOYOTA	YARIS	SCP10L	2001-2002	SCP10L 1000 1SZFE DOHC EFI HATCHBACK 2WD Door 5
P5452	TOYOTA	PLATZ	NCP12	1999-2000	NCP12 1NZFE 2WD
P5452	TOYOTA	PLATZ	NCP12	2000-2001	NCP12 1NZFE 2WD
P5452	TOYOTA	PLATZ	NCP12	2001-2002	NCP12 1NZFE 2WD
P5452	TOYOTA	PLATZ	NCP12	2002-2003	NCP12 1NZFE 2WD


Contact Supplier send an enquiry to
confirm suitable car




**Shock absorber
(structure chart)**



**Piston valve assembly
(Schematic diagram)**



**Bottom valve assembly
(Schematic diagram)**



It can restrain the vibration of spring and absorb the energy of road bump influence. It not only affects the riding comfort, but also affects the driving safety, and may cause the damage of other parts if the shock absorber is broken.

The shock absorber is a part need to replace regularly and it's service life is around 80000 km. Even if the shock absorber is not broken, it should be replaced, because the internal part of shock absorber has been worn and tear, it is impossible to judge whether the shock absorber is damaged from the product appearance. To avoid traffic safety issues, replace the shock absorber in time is necessary, and the shock absorbers need to be replaced in pairs to ensure the balance of the vehicle handling and the best driving performance.

How to check if the shock absorber needs to be replaced?

- ① Park the car on a flat road, press both sides manually or press the bumper hard with the foot id open (or press front part of the car), then release hands. If the vehicle stops after rebounds in 2-3 seconds, shock absorber is regarded as to be replacement needed.
- ② When suddenly brake the car at low speed, the car shakes violently, and the human body feels uncomfortable, shock absorber is highly probably broken.
- ③ The car stops after driving about 10km on the road with poor conditions, if you don't feel any temperature even cold by hand touch the housing of shock absorber, that is to say, shock absorber is not working normal due to no resistance internal itself.

SHOCK ABSORBER?

What advantage

1. No noise
2. No oil leakage
3. Durable and easy to control
4. More comfortable and stable





Stable Driving



No Oil Leaking



Anti-shaking



Noise Free



High
Temperature
Endurance



Long Lasting

SHOCK ABSORBER

Are you worried about the quality ?



Abnormal Noise?




oil Leaking?



Turning Bend?



Shock Absorber (structure chart)





Less Noise And More Comfortable !!

Quiet design only for your comfortable experience



Comfortable
driving



Increase braking
distance



Improve stability
and security

Reinstall in Situ Fit Perfectly



Product Details



HARDWARE METAL

High-strength piston rod, strong and wear-resistant



BRAND CODE

MASUMA product code identification



INSTALLATION

It can be replaced directly without any change



MASUMA

Note:

MASUMA auto parts covered more than 900,000 different OEM numbers, [here only show few parts.](#)
Pls Contact us to check more and details information for you.

Search For Car Brand (Click)	Auto parts	Product List	Number of suitable car models
For Japanes Car: For Toyota For Honda For Nissan For Mazda For Lexus For Infiniti For Mitsubishi For Suzuki For Subaru For DAIHATSU For ISUZU For Fuso	Auto Engine Systems	Air Filters	1215
		Fuel Filters	255
		Oil Filters	588
		Spark Plugs	59
		Engine Mounts	888
		Ignition Coils	255
		Ignition Cable	77
		Timing Chain Kit	67

		Cylinder Head Gaskets	223
		Ball Joints	655
For Korean Car:		Control Arms	394
For HYUNDAI		Rubber Bushing	685
For KIA		Shock Absorber Springs	153
		Shock Absorbers	323
For Europe Car:	Auto Suspension Systems	Stabilizer Links	453
For Benz		Suspension Strut	110
For BMW		Bearings	
For Audi		Brake Pads	1966
For VW		Brake Discs	825
For Porsche		Brake shoes	220
For Skoda			
For Renault			
For Peugeot			
For Volvo	Auto Brake Systems	Brake Cables	216
For Alfa Romeo		Brake Hoses	707
		Tie Rod Ends	345
For America Car:		Tie Rods (Rack End)	247
For Ford	Auto Steering Systems	Steering Gear Boots	435
For OPEL		Steering Gears	60
For Chevrolet			
	Air Conditioning Systems	Cabin Filters	736
		C.V. Joints	199
Other brand:		C.V. Joint Boots	157
For Land Rover	Auto Transmission Systems	Tensioner & Belts	1043
For Jeep		Wheel Hubs	103
For Ssangyong		Antifreeze	4
		Brake Lubricants	2
	Fluid & Chemicals	Engine Lubricants	42
		Transmission Fluids	15
		Other Auto Parts	5074
		Tire Repair Tools	57
		Auto Fastener & Clip	1881
	Other Auto Parts	Lug Nuts & Accessories	233
		Other Vehicle Tools	15

MASUMA

MAIN CAR SERIES

Cover 90% Of JAPANESE And KOREA Cars



Corolla



Crown



Camry



Civic



Tiida



Accord



RX300



RAV4



Golf



Passo



HR-V



Fortuner



Yaris



Avanza



Land Cruiser



Pajero(Montero)



Mirage



Stream



Hilux



CR-V



Legacy



Fit (jazz)



HiAce



X-Trail



Primera



Cedric



Mazda 3



Mazda 6



Prius



City



Impreza



Focus



[View more history >>](#)

MASUMA was founded in **1998 Japan**, integrates R&D, production, sales and operation as one. It has its own wholly-owned subsidiary factory and joint venture production base in **GuangZhou China**, have an area of **30,000 sqm**, **500+ employees** in the company, the annual turnover to reach 55 million USD. Masuma specializes in the design, development, manufacturing, sales and service of Japanese, German, American, Chinese and Korean auto parts. The current products include lubricating oil, transmission fluid, brake oil, brake pad, brake disc, filter, spark plug, ignition coil, ball joint, swing arm, shock absorber, belt, wiper, water tank cover and other series, over ten thousands of varieties, and products are sold to more than 100 countries and regions in the world.

MASUMA	1998			1
2011		30,000	500	55
Masuma				

100



Manufacturing Technique



PRECISION

Automated machinery

100,000 pieces/day



TAKAMAZ-FEELER



BROTHER SPEEDIO



TOYO



Mitutoyo QC



NGATA



KAWATA

Exhibition

EXHIBITION



MASUMA Masuma (Guangzhou) International Trading Co., Ltd.

+8615323309608

msm@masuma.com

masumajp.com

No. 19, Liwu Road, Tanbu Town, Huadu District, Guangzhou