P6506 MASUMA Rear Shock Absorbers for TOYOTA GRAND HIACE 48531-26540 48531-26550 48531-26710

Basic Information

• Place of Origin: Guangdong, China

Brand Name: MASUMA
Minimum Order Quantity: 2 pieces
Price: Negotiation
Packaging Details: carton

Supply Ability: 100000 Piece/Pieces per Week



Product Specification

Model: CRUZE (J300)Year: 2009-, 1995-2011

• OE NO.: 48531-26540, 48531-26550, 48531-26710,

48531-80459, 48531-80460, 48531-80636, 48531-80651, 48531-80226, 48531-80678, 48531-80679, 48531-80585, 344485, 48531-26590, 48531-26730, 48531-26740, 48531-

26760

Car Fitment: Chevrolet

• Reference NO.: BSG 65-300-034, 65-300-034, G8196

• Warranty: 12 Months, Warranty 12 Months Or 30

Thousand Kilometer

• Car Model: JAPAN

Product Name: Suspension Shock Absorber


MASUMA NO.: P6506Delivery Time: 3-7daysIn Stock: Yes

	Brand	Car model	Chassis number	Year	Configuration			
P6506	TOYOTA	GRAND HACE	KCH16W	1995-1997	KCH16W, 1KZTE, TURBO, 4WD			
PESOS	TOYOTA	GRAND HACE	KCH16W	1997-1999	KCH16W 1KZTE TURBO 4WD			
P6506	TOYOTA	GRAND HACE	KCH16W	1999-2000	KCH16W 1KZTE TURBO 4WD			
P6506	TOYOTA	GRAND HACE	KCH16W	1999-2002	KCH16W, 1KZTE, TURBO, 4WD			
P6506	TOYOTA	GRAND HACE	VCH16W	1997-1999	VCH16W, SVZFE, 4WD			
P6506	TOYOTA	GRAND HACE	VCH16W	1999-2002	VCH16W, SVZFE, 4WD			
P6506	TOYOTA	GRAND HACE	VCH28K	1999-2005	VCH28K, 5VZFE, 4WD			
P6506	TOYOTA	GRANNA	KCH16W	1995-1997	KCH16W, 1KZTE, TURBO, 4WD			
P6506	TOYOTA	GRANNA	KCH16W	1997-1999	KCH16W, 1KZTE, TURBO, 4WD			
P6506	TOYOTA	GRANNA	KCH16W	1999-2000	KCH16W, 1KZTE, TURBO, 4WD			
P6506	TOYOTA	GRANNA	KCH16W	1999-2002	KCH16W, 1KZTE, TURBO, 4WD			
P6506	TOYOTA	GRANNA	VCH16W	1997-1999	VCH16W, SVZFE, 4WD			
P6506	TOYOTA	GRANNA	VCH16W	1999-2002	VCH16W, SVZFE, 4WD			
P6506	TOYOTA	GRANNA	VCH28K	1999-2005	VCH28K SVZFE 4WD			
P6506	TOYOTA	HACE	10.1146		KLH12L 2500 2KDFTV DOHC TURBO			
P6506	TOYOTA	HACE	KLH12L	2001-2004	MICROBUSIVAN, 2WD, Door 4			
PRESON	TOYOTA	HACE	KLH12L	2001-2004	KLH12L 2500 2KDFTV DOHC TURBO.			
Pessue	IOTOIA	MACE	KLHIZL		MICROBUSIVAN, 2WD, Door 5			
P6506	TOYOTA	HACE	KI.H12L	2004-2006	KLH12L 2500 2KDFTV DOHC TURBO.			
P6506			RLH12L		MICROBUSIVAN, 2WD, Deer 4			
P6506	TOYOTA	HACE	KLH12L	2004-2006	KLH12L 2500 2KDFTV DOHC TURBO.			
					MICROBUSIVAN, 2WD, Door 5			
	TOYOTA	HACE		2006-2011	KLH12L 2500 2KDFTV DOHC			
P6506			KI.H12L		INTERCOOLER TURBO, MICROBUSAVAN			
					2WD. Door 4			
					KLH12L 2500 2KDFTV DOHC			
P6506	TOYOTA	HACE	KLH12L	2006-2011	INTERCOOLER TURBO, MICROBUSIVAN.			
			-		2WD. Door 5			
P6506	TOYOTA	HACE		2001,2004	KLH18L 2500 2KDFTV DOHC TURBO			
P6506	IOYOIA	HACE	KLH18L	2001-2004	MICROBUSIVAN 4WD Door 5			
P6506	TOYOTA	HACE	KLH18L	2004-2011	KLH18L 2500 2KDFTV DOHC TURBO			
P6506	IOYOTA	HACE	KLH18L	2004-2011	MICROBUSIVAN 4WD Door 5			
					KLH18L, 2500, 2KDFTV, DOHC.			
P6506	TOYOTA	HACE	KLH18L	2008-2010	INTERCOOLER TURBO, MICROBUS/VAN.			
					4WD. Door 4			
P6506	TOYOTA	HACE	KI H18L	2008-2011	KLH18L 2500 2KDFTV DOHC TURBO			
P0000	IOTOIA	HMCE	KLH18L	2008-2011	MICROBUSIVAN 4WD Door 5			
Pesos	TOYOTA				KLH22L 2500 2KDFTV DOHC TURBO			
P6506	ATOYOTA	HACE	KLH22L	2001-2004	MICROBUSIVAN 2WD Door 4			
01111					KLH22L 2500 2KDFTV DOHC TURBO			
70000	ont	act Cum	plior cond	1 00	enquiry to			
	JUILLE	act oup	pher sent	a an	enquiry to			
		con	confirm suitable car					
		0011	m m Suita	DIO (Town Door A			

More Images







Product Description

MASUMA No.

Part Name Suspension shock absorber

4853,48531-26540,48531-26550,48531-26710,48531-80226,48531-80459,48531-80460,48531-

80636,48531-80651

Maintenance Warranty 12 months or 30 thousand kilometer

In stock Contact for inventory


Masuma shocks are manufactured to original OEM specifications. Masuma struts and shock absorbers are not tuning, but a quality replacement for original parts with additional improvements. The stems of Masuma shock absorbers have micronotches that help lubricate the stem packing. This extends the life of the oil seal and the entire shock absorber. Shock absorbers are guaranteed for 12 months. Wherever you bought or installed a part, within a year you have the right to return it by simply providing him with a receipt or other document confirming the purchase date and price. Even if you are not a certified auto mechanic and installed the part yourself in your garage, just keep your purchase receipt and, if a problem arises, you can always return the part. Masuma is a global brand of auto parts, components and consumables. The main specialization of the brand: resource parts for post-warranty service of Japanese cars. The company's strategy is to offer consumers the best ratio of reliability and cost of spare parts.


SUITABLE FOR CAR MODELS DETAILS MASUMA **Brand** Car model Chassis number Year Configuration KLH12L 2500 2KDFTV DOHC INTERCOOLER TURBO P6506 TOYOTA HIACE KLH12L 2006-2011 MICROBUS/VAN. 2WD. Door 4 KLH12L. 2500. 2KDFTV. DOHC. INTERCOOLER TURBO. P6506 TOYOTA HIACE 2006-2011 MICROBUS/VAN, 2WD, Door 5 KLH18L, 2500, 2KDFTV, DOHC, INTERCOOLER TURBO. P6506 TOYOTA HIACE KLH18L 2008-2010 MICROBUS/VAN. 4WD. Door 4 KLH22L. 2500. 2KDFTV. DOHC. INTERCOOLER TURBO. P6506 KLH22L 2006-2011 TOYOTA HIACE MICROBUS/VAN. 2WD. Door 4 KLH22L. 2500, 2KDFTV. DOHC. INTERCOOLER TURBO. P6506 TOYOTA HIACE KLH22L 2006-2011 MICROBUS/VAN. 2WD. Door 5 KLH28L. 2500. 2KDFTV. DOHC. INTERCOOLER TURBO 2006-2011 P6506 TOYOTA HIACE KLH28L MICROBUS/VAN, 4WD, Door 5 KLH12L, 2500, 2KDFTV, DOHC, TURBO P6506 TOYOTA HIACE KLH12L 2001-2004 MICROBUS/VAN. 2WD. Door 4 KLH12L. 2500. 2KDFTV. DOHC. TURBO P6506 TOYOTA HIACE KLH12L 2001-2004 MICROBUS/VAN 2WD Door 5 KLH12L 2500 2KDFTV DOHC TURBO MICROBUS/VAN 2WD Door 4 KLH12L 2500 2KDFTV DOHC TURBO P6506 TOYOTA HIACE KLH12L 2004-2006 KLH12L P6506 TOYOTA HIACE 2004-2006 MICROBUS/VAN. 2WD. Door 5 KLH18L 2500. 2KDFTV. DOHC. TURBO. MICROBUS/VAN. 4WD. Door 5 KLH18L. 2500. 2KDFTV. DOHC. TURBO. KLH18L P6506 TOYOTA HIACE 2001-2004 KLH18L 2004-2011 P6506 TOYOTA HIACE MICROBUS/VAN. 4WD. Door 5 KLH18L. 2500. 2KDFTV. DOHC. TURBO TOYOTA HIACE KLH18L 2008-2011 MICROBUS/VAN. 4WD. Door 5 KLH22L. 2500. 2KDFTV. DOHC. TURBO HIACE KLH22L 2001-2004 P6506 TOYOTA MICROBUS/VAN. 2WD. Door 4 KLH22L 2500. 2KDFTV. DOHC. TURBO. KLH22L P6506 TOYOTA MICROBUS/VAN. 2WD. Door 5 KLH22L. 2500. 2KDFTV. DOHC. TURBO. P6506 TOYOTA HIACE KLH22L 2004-2006 MICROBUS/VAN. 2WD. Door 4 KLH22L 2500. 2KDFTV. DOHC. TURBO KLH22L TOYOTA MICROBUS/VAN. 2WD. Door 5 KLH28L. 2500. 2KDFTV. DOHC. TURBO P6506 TOYOTA HIACE KLH28I 2001-2004 MICROBUS/VAN, 4WD, Door 5 KLH28L, 2500, 2KDFTV, DOHC, TURBO P6506 TOYOTA HIACE 2004-2006 MICROBUS/VAN. 4WD. Door 5 LXH12L, 2400, 2LT, SOHC, TURBO, MICROBUS/VAN P6506 TOYOTA HIACE LXH12L 1999-2001 2WD. Door 4 LXH12L. 2400. 2LT. SOHC. TURBO. MICROBUS/VAN. P6506 TOYOTA 2WD. Door 5 LXH18L, 2400, 2LT, SOHC, TURBO, MICROBUS/VAN.

Contact Supplier send an enquiry to confirm suitable car












It can restrain the vibration of spring and absorb the energy of road bump arfluence. It not only affects the riding comfort, but also affects the driving safety, and may cause the damage of

The shock absorber is a part need to uplace regularly and the service He is award SEOOS by Level the of occe deboter in not crosses in distance because the shorter has been worned that is, it is independent to uplace whether the discolation has demanded that the product observations of the crosses of the product observations of the crosses of the product observations of the crosses of the shock deboter has the crosses of the shock deboter has extended the crosses of the shock deboter has read to ensure the billiance of the vertical hashing and the cross thrains or timeses.

How to check if the shock absorber needs to be replaced?

- Province heat with the book listened or of press float part of the own, then release bonds. If the which stops after rebunds in 2-3 as seconds, shock elseother is reparted as to be replacement needed & When sudderly brake the care at low speed, the care shakes visited by When sudderly brake the care at low speed, the care shakes when yeard the human body feets uncomfortable, shock elseother is highly probably broken.
- The cer stops after driving about 10km on the road with poor conditions, if you don't feel any temperature even cold by hand touch the housing of shock absorber that is to say, shock obsorber is not working normal due to no resistance internal itself.





Stable Driving



No Oil Leaking



Anti-shaking



Noise Free




High Temperature Endurance




Long Lasting



Are you worried about the quality?







Less Noise And More Comfortable !!

Quiet design only for your comfortable experience









Reinstall in Situ Fit Perfectly





MASUMA

Note:

MASUMA auto parts covered more than 900,000 different OEM numbers, <u>here only show few parts.</u> Pls Contact us to check more and details information for you.

Search For Car Brand Click)	Auto parts	Product List	Number of suitable car models
		Air Filters	1215
For Japanes Car:		Fuel Filters	255
For Toyota For Honda For Nissan		Oil Filters	588
For Mazda		Spark Plugs	59
For Lexus For Infiniti		Engine Mounts	888
For Mitsubishi For Suzuki For Subaru	Auto Engine Systems	Ignition Coils	255
For DAIHATSU		Ignition Cable	77
For ISUZU For Fuso		Timing Chain Kit	67

		Cylinder Head Gaskets	223
		Ball Joints	655
For Korean Car:		Control Arms	394
For HYUNDAI For KIA		Rubber Bushing	685
		Shock Absorber Springs	153
	Auto Cuononcian Cyctoma	Shock Absorbers	323
For Europe Car:	Auto Suspension Systems	Stabilizer Links	453
For Benz For BMW		Suspension Strut Bearings	110
For Audi For VW		Brake Pads	1966
For Porsche For Skoda		Brake Discs	825
For Renault For Peugeot		Brake shoes	220
For Volvo For Alfa Romeo	Auto Brake Systems	Brake Cables	216
		Brake Hoses	707
		Tie Rod Ends	345
For America Car:		Tie Rods (Rack End)	247
For Ford For OPEL	Auto Steering Systems	Steering Gear Boots	435
For Chevrolet		Steering Gears	60
	Air Conditioning Systems	Cabin Filters	736
Other burnels		C.V. Joints	199
Other brand:		C.V. Joint Boots	157
For Land Rover For Jeep	Auto Transmission Systems	Tensioner & Belts	1043
For Ssangyong	.,	Wheel Hubs	103
		Antifreeze	4
		Brake Lubricants	2
	Fluid & Chemicals	Engine Lubricants	42
		Transmission Fluids	15
		Other Auto Parts	5074
		Tire Repair Tools	57
		Auto Fastener & Clip	1881
	Other Auto Parts	Lug Nuts & Accessories	233
		Other Vehicle Tools	15



Cover 90% Of JAPANESE And KOREA Cars



Corolla



Crown



Camry



Civic



Tiida



Accord



RX300



RAV4



Golf



Passo



HR-V



Fortuner



Yaris



Avanza



Land Cruiser



Pajero (Montero)



Mirage



Stream



Hilux



CR-V



Legacy



Fit (jazz)



HiAce



X-Trail



Primera



Cedric



Mazda 3



Mazda 6





City



Impreza



Focus



Company Profile



MASUMA was founded in 1998 Japan, integrates R&D, production, sales and operation as one. It has its own

wholly-owned subsidiary factory and joint venture production base in**GuangZhou China**, have an area of **30,000 sqm**, **500+ employees** in the company, the annual turnover to reach 55 million USD. Masuma specializes in the design, development, manufacturing, sales and service of Japanese, German, American, Chinese and Korean auto parts. The current products include lubricating oil, transmission fluid, brake oil, brake pad, brake disc, filter, spark plug, ignition coil, ball joint, swing arm, shock absorber, belt, wiper, water tank cover and other series, over ten thousands of varieties, and products are sold to more than 100 countries and regions in the world.

MASUMA 1998 1 2011 30,000 500 55 Masuma



Manufacturing Technique



PRECISION

Automated machinery

100,000 pieces/day









TAKAMAZ-FEELER

BROTHER SPEEDIO

TOYO







Exhibition



MASUMA Masuma (Guangzhou) International Trading Co., Ltd.

+8615323309608



msm@masuma.com



masumajp.com