

Shock Absorbers 48540-33010 for TOYOTA CAMRY 48530-33010 48530-33020 48530-80126 CV30

Our Product Introduction

Basic Information

- Place of Origin: Guangdong, China
- Brand Name: MASUMA
- Minimum Order Quantity: 2 pieces
- Price: Negotiation
- Packaging Details: carton
- Supply Ability: 100000 Piece/Pieces per Week

MASUMA
 AUTO SPARE PARTS


Product Specification

- Model: CAMRY (_V1_), CAMRY Station Wagon (_V1_)
- Year: 1991-1997, 1991-1997, 1990-1998
- OE NO.: 48540-33010, 48530-33010, 48530-33020, 48530-80126, 48540-39195, 48540-39525, 48540-33020, 48540-32220, 48540-32230, 48540-39115, 48540-39125, 48540-39145, 48530-32220, 48530-32230, 48530-39165, 48530-39175, 48530-39195, 365097
- Car Fitment: Toyota
- Reference NO.: 32-G44-A, 365097, 280554, MG256, 32-E58-A, 230239, JGC104S, JGC104T, G22068LR, Z3154, N5522103G, 4214-0032-SX, G55676, 178824, DG 7946, 32-G43-A, 334133, 230 239, 280 553, VNE-4958
- Warranty: 12 Months, Warranty 12 Months Or 30 Thousand Kilometer
- Car Model: JAPAN
- Product Name: Suspension Shock Absorber

MASUMA	Brand	Car model	Chassis number	Year	Configuration
71118	TOYOTA	CAMRY	CV30	1990-1994	CV30 3CT TURBO 2WD
71118	TOYOTA	CAMRY	CV40	1994-1998	CV40 3CT TURBO 2WD
71118	TOYOTA	CAMRY	SV30	1990-1994	SV30 4SE 2WD
71118	TOYOTA	CAMRY	SV40	1994-1998	SV40 4SE 2WD
71118	TOYOTA	CAMRY	SV41	1994-1998	SV41 3SE 2WD
71118	TOYOTA	CAMRY	SV42	1994-1998	SV42 3SE 2WD
71118	TOYOTA	CAMRY	SVX0L	1991-1994	SVX0L 2000 55FE DOHC EFI SEDAN 2000 55FE 4
71118	TOYOTA	CAMRY	SVX0L	1994-1996	SVX0L 2000 55FE DOHC EFI SEDAN 2000 55FE 4
71118	TOYOTA	CAMRY	VCV0L	1991-1994	VCV0L 3000 3ZFE DOHC EFI SEDAN 2000 55FE 4
71118	TOYOTA	CAMRY	VCV0L	1994-1996	VCV0L 3000 3ZFE DOHC EFI SEDAN 2000 55FE 4
71118	TOYOTA	SCPIER	SVX0	1992-1994	SVX0 1994 55FE 2WD
71118	TOYOTA	SCPIER	SVX0	1994-1996	SVX0 1994 55FE 2WD
71118	TOYOTA	SCPIER	SVX0	1996-1998	SVX0 1994 55FE 2WD
71118	TOYOTA	SCPIER	SVX0	1998-1999	SVX0 1994 55FE 2WD
71118	TOYOTA	SCPIER	SVX0	1999-2000	SVX0 1994 55FE 2WD
71118	TOYOTA	SCPIER	SVX0	2000-2001	SVX0 1994 55FE 2WD
71118	TOYOTA	SCPIER	SVX0	2001-2002	SVX0 1994 55FE 2WD
71118	TOYOTA	SCPIER	SVX0	2002-2003	SVX0 1994 55FE 2WD
71118	TOYOTA	SCPIER	SVX0	2003-2004	SVX0 1994 55FE 2WD
71118	TOYOTA	SCPIER	SVX0	2004-2005	SVX0 1994 55FE 2WD
71118	TOYOTA	SCPIER	SVX0	2005-2006	SVX0 1994 55FE 2WD
71118	TOYOTA	SCPIER	SVX0	2006-2007	SVX0 1994 55FE 2WD
71118	TOYOTA	SCPIER	SVX0	2007-2008	SVX0 1994 55FE 2WD
71118	TOYOTA	SCPIER	SVX0	2008-2009	SVX0 1994 55FE 2WD
71118	TOYOTA	SCPIER	SVX0	2009-2010	SVX0 1994 55FE 2WD
71118	TOYOTA	SCPIER	SVX0	2010-2011	SVX0 1994 55FE 2WD
71118	TOYOTA	SCPIER	SVX0	2011-2012	SVX0 1994 55FE 2WD
71118	TOYOTA	SCPIER	SVX0	2012-2013	SVX0 1994 55FE 2WD
71118	TOYOTA	SCPIER	SVX0	2013-2014	SVX0 1994 55FE 2WD
71118	TOYOTA	SCPIER	SVX0	2014-2015	SVX0 1994 55FE 2WD
71118	TOYOTA	SCPIER	SVX0	2015-2016	SVX0 1994 55FE 2WD
71118	TOYOTA	SCPIER	SVX0	2016-2017	SVX0 1994 55FE 2WD
71118	TOYOTA	SCPIER	SVX0	2017-2018	SVX0 1994 55FE 2WD
71118	TOYOTA	SCPIER	SVX0	2018-2019	SVX0 1994 55FE 2WD
71118	TOYOTA	SCPIER	SVX0	2019-2020	SVX0 1994 55FE 2WD
71118	TOYOTA	SCPIER	SVX0	2020-2021	SVX0 1994 55FE 2WD
71118	TOYOTA	SCPIER	SVX0	2021-2022	SVX0 1994 55FE 2WD
71118	TOYOTA	SCPIER	SVX0	2022-2023	SVX0 1994 55FE 2WD
71118	TOYOTA	SCPIER	SVX0	2023-2024	SVX0 1994 55FE 2WD
71118	TOYOTA	SCPIER	SVX0	2024-2025	SVX0 1994 55FE 2WD
71118	TOYOTA	SCPIER	SVX0	2025-2026	SVX0 1994 55FE 2WD
71118	TOYOTA	SCPIER	SVX0	2026-2027	SVX0 1994 55FE 2WD
71118	TOYOTA	SCPIER	SVX0	2027-2028	SVX0 1994 55FE 2WD
71118	TOYOTA	SCPIER	SVX0	2028-2029	SVX0 1994 55FE 2WD
71118	TOYOTA	SCPIER	SVX0	2029-2030	SVX0 1994 55FE 2WD
71118	TOYOTA	SCPIER	SVX0	2030-2031	SVX0 1994 55FE 2WD
71118	TOYOTA	SCPIER	SVX0	2031-2032	SVX0 1994 55FE 2WD
71118	TOYOTA	SCPIER	SVX0	2032-2033	SVX0 1994 55FE 2WD
71118	TOYOTA	SCPIER	SVX0	2033-2034	SVX0 1994 55FE 2WD
71118	TOYOTA	SCPIER	SVX0	2034-2035	SVX0 1994 55FE 2WD
71118	TOYOTA	SCPIER	SVX0	2035-2036	SVX0 1994 55FE 2WD
71118	TOYOTA	SCPIER	SVX0	2036-2037	SVX0 1994 55FE 2WD
71118	TOYOTA	SCPIER	SVX0	2037-2038	SVX0 1994 55FE 2WD
71118	TOYOTA	SCPIER	SVX0	2038-2039	SVX0 1994 55FE 2WD
71118	TOYOTA	SCPIER	SVX0	2039-2040	SVX0 1994 55FE 2WD
71118	TOYOTA	SCPIER	SVX0	2040-2041	SVX0 1994 55FE 2WD
71118	TOYOTA	SCPIER	SVX0	2041-2042	SVX0 1994 55FE 2WD
71118	TOYOTA	SCPIER	SVX0	2042-2043	SVX0 1994 55FE 2WD
71118	TOYOTA	SCPIER	SVX0	2043-2044	SVX0 1994 55FE 2WD
71118	TOYOTA	SCPIER	SVX0	2044-2045	SVX0 1994 55FE 2WD
71118	TOYOTA	SCPIER	SVX0	2045-2046	SVX0 1994 55FE 2WD
71118	TOYOTA	SCPIER	SVX0	2046-2047	SVX0 1994 55FE 2WD
71118	TOYOTA	SCPIER	SVX0	2047-2048	SVX0 1994 55FE 2WD
71118	TOYOTA	SCPIER	SVX0	2048-2049	SVX0 1994 55FE 2WD
71118	TOYOTA	SCPIER	SVX0	2049-2050	SVX0 1994 55FE 2WD
71118	TOYOTA	SCPIER	SVX0	2050-2051	SVX0 1994 55FE 2WD
71118	TOYOTA	SCPIER	SVX0	2051-2052	SVX0 1994 55FE 2WD
71118	TOYOTA	SCPIER	SVX0	2052-2053	SVX0 1994 55FE 2WD
71118	TOYOTA	SCPIER	SVX0	2053-2054	SVX0 1994 55FE 2WD
71118	TOYOTA	SCPIER	SVX0	2054-2055	SVX0 1994 55FE 2WD
71118	TOYOTA	SCPIER	SVX0	2055-2056	SVX0 1994 55FE 2WD
71118	TOYOTA	SCPIER	SVX0	2056-2057	SVX0 1994 55FE 2WD
71118	TOYOTA	SCPIER	SVX0	2057-2058	SVX0 1994 55FE 2WD
71118	TOYOTA	SCPIER	SVX0	2058-2059	SVX0 1994 55FE 2WD
71118	TOYOTA	SCPIER	SVX0	2059-2060	SVX0 1994 55FE 2WD
71118	TOYOTA	SCPIER	SVX0	2060-2061	SVX0 1994 55FE 2WD
71118	TOYOTA	SCPIER	SVX0	2061-2062	SVX0 1994 55FE 2WD
71118	TOYOTA	SCPIER	SVX0	2062-2063	SVX0 1994 55FE 2WD
71118	TOYOTA	SCPIER	SVX0	2063-2064	SVX0 1994 55FE 2WD
71118	TOYOTA	SCPIER	SVX0	2064-2065	SVX0 1994 55FE 2WD
71118	TOYOTA	SCPIER	SVX0	2065-2066	SVX0 1994 55FE 2WD
71118	TOYOTA	SCPIER	SVX0	2066-2067	SVX0 1994 55FE 2WD
71118	TOYOTA	SCPIER	SVX0	2067-2068	SVX0 1994 55FE 2WD
71118	TOYOTA	SCPIER	SVX0	2068-2069	SVX0 1994 55FE 2WD
71118	TOYOTA	SCPIER	SVX0	2069-2070	SVX0 1994 55FE 2WD
71118	TOYOTA	SCPIER	SVX0	2070-2071	SVX0 1994 55FE 2WD
71118	TOYOTA	SCPIER	SVX0	2071-2072	SVX0 1994 55FE 2WD
71118	TOYOTA	SCPIER	SVX0	2072-2073	SVX0 1994 55FE 2WD
71118	TOYOTA	SCPIER	SVX0	2073-2074	SVX0 1994 55FE 2WD
71118	TOYOTA	SCPIER	SVX0	2074-2075	SVX0 1994 55FE 2WD
71118	TOYOTA	SCPIER	SVX0	2075-2076	SVX0 1994 55FE 2WD
71118	TOYOTA	SCPIER	SVX0	2076-2077	SVX0 1994 55FE 2WD
71118	TOYOTA	SCPIER	SVX0	2077-2078	SVX0 1994 55FE 2WD
71118	TOYOTA	SCPIER	SVX0	2078-2079	SVX0 1994 55FE 2WD
71118	TOYOTA	SCPIER	SVX0	2079-2080	SVX0 1994 55FE 2WD
71118	TOYOTA	SCPIER	SVX0	2080-2081	SVX0 1994 55FE 2WD
71118	TOYOTA	SCPIER	SVX0	2081-2082	SVX0 1994 55FE 2WD
71118	TOYOTA	SCPIER	SVX0	2082-2083	SVX0 1994 55FE 2WD
71118	TOYOTA	SCPIER	SVX0	2083-2084	SVX0 1994 55FE 2WD
71118	TOYOTA	SCPIER	SVX0	2084-2085	SVX0 1994 55FE 2WD
71118	TOYOTA	SCPIER	SVX0	2085-2086	SVX0 1994 55FE 2WD
71118	TOYOTA	SCPIER	SVX0	2086-2087	SVX0 1994 55FE 2WD
71118	TOYOTA	SCPIER	SVX0	2087-2088	SVX0 1994 55FE 2WD
71118	TOYOTA	SCPIER	SVX0	2088-2089	SVX0 1994 55FE 2WD
71118	TOYOTA	SCPIER	SVX0	2089-2090	SVX0 1994 55FE 2WD
71118	TOYOTA	SCPIER	SVX0	2090-2091	SVX0 1994 55FE 2WD
71118	TOYOTA	SCPIER	SVX0	2091-2092	SVX0 1994 55FE 2WD
71118	TOYOTA	SCPIER	SVX0	2092-2093	SVX0 1994 55FE 2WD
71118	TOYOTA	SCPIER	SVX0	2093-2094	SVX0 1994 55FE 2WD
71118	TOYOTA	SCPIER	SVX0	2094-2095	SVX0 1994 55FE 2WD
71118	TOYOTA	SCPIER	SVX0	2095-2096	SVX0 1994 55FE 2WD
71118	TOYOTA	SCPIER	SVX0	2096-2097	SVX0 1994 55FE 2WD
71118	TOYOTA	SCPIER	SVX0	2097-2098	SVX0 1994 55FE 2WD
71118	TOYOTA	SCPIER	SVX0	2098-2099	SVX0 1994 55FE 2WD
71118	TOYOTA	SCPIER	SVX0	2099-2100	SVX0 1994 55FE 2WD
71118	TOYOTA	SCPIER	SVX0	2100-2101	SVX0 1994 55FE 2WD
71118	TOYOTA	SCPIER	SVX0	2101-2102	SVX0 1994 55FE 2WD
71118	TOYOTA	SCPIER	SVX0	2102-2103	SVX0 1994 55FE 2WD
71118	TOYOTA	SCPIER	SVX0	2103-2104	SVX0 1994 55FE 2WD
71118	TOYOTA	SCPIER	SVX0	2104-2105	SVX0 1994 55FE 2WD
71118	TOYOTA	SCPIER	SVX0	2105-2106	SVX0 1994 55FE 2WD
71118	TOYOTA	SCPIER	SVX0	2106-2107	SVX0 1994 55FE 2WD
71118	TOYOTA	SCPIER	SVX0	2107-2108	SVX0 1994 55FE 2WD
71118	TOYOTA	SCPIER	SVX0	2108-2109	SVX0 1994 55FE 2WD
71118	TOYOTA	SCPIER	SVX0	2109-2110	SVX0 1994 55FE 2WD
71118	TOYOTA	SCPIER	SVX0	2110-2111	SVX0 1994 55FE 2WD
71118	TOYOTA	SCPIER	SVX0	2111-2112	SVX0 1994 55FE 2WD
71118	TOYOTA	SCPIER	SVX0	2112-2113	SVX0 1994 55FE 2WD
71118	TOYOTA	SCPIER	SVX0	2113-2114	SVX0 1994 55FE 2WD
71118	TOYOTA	SCPIER	SVX0	2114-2115	SVX0 1994 55FE 2WD
71118	TOYOTA	SCPIER	SVX0	2115-2116	SVX0 1994 55FE 2WD
71118	TOYOTA	SCPIER	SVX0	2116-2117	SVX0 1994 55FE 2WD
71118	TOYOTA	SCPIER	SVX0	2117-2118	SVX0 1994 55FE 2WD
71118	TOYOTA	SCPIER	SVX0	2118-2119	SVX0 1994 55FE 2WD
71118	TOYOTA	SCPIER	SVX0	2119-2120	SVX0 1994 55FE 2WD
71118	TOYOTA	SCPIER	SVX0	2120-2121	SVX0 1994 55FE 2WD
71118	TOYOTA	SCPIER	SVX0	2121-2122	SVX0 1994 55FE 2WD
71118	TOYOTA	SCPIER	SVX0	2122-2123	SVX0 1994 55FE 2WD
71118	TOYOTA	SCPIER	SVX0	2123-2124	SVX0 1994 55FE 2WD
71118	TOYOTA	SCPIER	SVX0	2124-2125	SVX0 1994 55FE 2WD
71118	TOYOTA	SCPIER	SVX0	2125-2126	SVX0 1994 55FE 2WD
71118	TOYOTA	SCPIER	SVX0	2126-2127	SVX0 1994 55FE 2WD
71118	TOYOTA	SCPIER	SVX0	2127-2128	SVX0 1994 55FE 2WD
71118	TOYOTA	SCPIER	SVX0	2128-2129	SVX0 1994 55FE 2WD
71118	TOYOTA	SCPIER	SVX0	2129-2130	SVX0 1994 55FE 2WD
71118	TOYOTA	SCPIER	SVX0	2130-2131	SVX0 1994 55FE 2WD
71118	TOYOTA	SCPIER	SVX0	2131-2132	SVX0 1994 55FE 2WD
71118	TOYOTA	SCPIER	SVX0	2132-2133	SVX0 1994 55FE 2WD
71118	TOYOTA	SCPIER	SVX0	2133-2134	SVX0 1994 55FE 2WD
71118	TOYOTA	SCPIER	SVX0	2134-2135	SVX0 1994 55FE 2WD
71118	TOYOTA	SCPIER	SVX0	2135-2136	SVX0 1994 55FE 2WD
71118	TOYOTA	SCPIER	SVX0	2136-2137	SVX0 1994 55FE 2WD
71118	TOYOTA	SCPIER	SVX0	2137-2138	SVX0 1994 55FE 2WD
71118	TOYOTA	SCPIER	SVX0	2138-2139	SVX0 1994 55FE 2WD
71118	TOYOTA	SCPIER	SVX0	2139-2140	SVX0 1994 55FE 2WD
71118	TOYOTA	SCPIER	SVX0	2140-2141	SVX0 1994 55FE 2WD
71118	TOYOTA	SCPIER	SVX0	2141-2142	SVX0 1994 55FE 2WD
71118	TOYOTA	SCPIER	SVX0	2142-2143	SVX0 1994 55FE 2WD
71118	TOYOTA	SCPIER	SVX0	2143-2144	SVX0 1994 55FE 2WD
71118	TOYOTA	SCPIER	SVX0	2144-2145	SVX0 1994 55FE 2WD
71118	TOYOTA	SCPIER	SVX0	2145-2146	SVX0 1994 55FE 2WD
71118	TOYOTA	SCPIER	SVX0	2146-2147	SVX0 1994 55FE 2WD
71118	TOYOTA	SCPIER	SVX0	2147-2148	SVX0 1994 55FE 2WD
71118	TOYOTA	SCPIER	SVX0	2148-2149	SVX0 1994 55FE 2WD
71118	TOYOTA	SCPIER	SVX0	2149-2150	SVX0 1994 55FE 2WD
71118	TOYOTA	SCPIER	SVX0	2150-2151	SVX0 1994 55FE 2WD
71118	TOYOTA	SCPIER	SVX0	2151-2152	SVX0 1994 55FE 2WD
71118	TOYOTA	SCPIER	SVX0	2152-2153	SVX0 1994 55FE 2WD
71118	TOYOTA	SCPIER	SVX0	2153-2154	SVX0 1994 55FE 2WD
71118	TOYOTA	SCPIER	SVX0	2154-2155	SVX0 1994 55FE 2WD
71118	TOYOTA	SCPIER	SVX0	2155-2156	SVX0 1994 55FE 2WD
7111					

Product Description

Product Description

MASUMA No. T7118

Part Name Suspension shock absorber

OEM No. 365097,48530-32220,48530-32230,48530-33010,48530-33020,48530-39165,48530-39175,48530-39195,48530-80126,48540-32220,48540-32230,48540-33010,48540-33020,48540-39115,48540-39125,48540-39145,48540-39195,48540-39525

Maintenance Warranty 12 months or 30 thousand kilometer

In stock Contact for inventory

Masuma shocks are manufactured to original OEM specifications. Masuma struts and shock absorbers are not tuning, but a quality replacement for original parts with additional improvements. The stems of Masuma shock absorbers have micro-notches that help lubricate the stem packing. This extends the life of the oil seal and the entire shock absorber. Shock absorbers are guaranteed for 12 months. Wherever you bought or installed a part, within a year you have the right to return it by simply providing him with a receipt or other document confirming the purchase date and price. Even if you are not a certified auto mechanic and installed the part yourself in your garage, just keep your purchase receipt and, if a problem arises, you can always return the part. Masuma is a global brand of auto parts, components and consumables. The main specialization of the brand: resource parts for post-warranty service of Japanese cars. The company's strategy is to offer consumers the best ratio of reliability and cost of spare parts.

SUITABLE FOR CAR MODELS DETAILS

MASUMA	Brand	Car model	Chassis number	Year	Configuration
T7118	TOYOTA	CAMRY	VCV10L	1991-1994	VCV10L 3000. 3VZFE. DOHC. EFI. SEDAN. 2WD. Door 4
T7118	TOYOTA	CAMRY	VCV10L	1994-1996	VCV10L 3000. 3VZFE. DOHC. EFI. SEDAN. 2WD. Door 4
T7118	TOYOTA	CAMRY	SXV10L	1991-1994	SXV10L 2200. 5SFE. DOHC. EFI. SEDAN. 2WD. Door 4
T7118	TOYOTA	CAMRY	SXV10L	1994-1996	SXV10L 2200. 5SFE. DOHC. EFI. SEDAN. 2WD. Door 4
T7118	TOYOTA	CAMRY	CV30	1990-1994	CV30. 2CT. TURBO. 2WD
T7118	TOYOTA	CAMRY	CV40	1994-1998	CV40. 3CT. TURBO. 2WD
T7118	TOYOTA	VISTA	CV30	1990-1994	CV30. 2CT. TURBO. 2WD
T7118	TOYOTA	VISTA	CV40	1994-1998	CV40. 3CT. TURBO. 2WD
T7118	TOYOTA	SCEPTER	SXV10	1992-1994	SXV10. 5SFE. 2WD
T7118	TOYOTA	SCEPTER	SXV10	1994-1996	SXV10. 5SFE. 2WD
T7118	TOYOTA	SCEPTER	SXV15	1993-1994	SXV15. 5SFE. 2WD
T7118	TOYOTA	SCEPTER	SXV15	1994-1996	SXV15. 5SFE. 2WD
T7118	TOYOTA	CAMRY	SV30	1990-1994	SV30. 4SFE. 2WD
T7118	TOYOTA	CAMRY	SV40	1994-1998	SV40. 4SFE. 2WD
T7118	TOYOTA	CAMRY	SV41	1994-1998	SV41. 3SFE. 2WD
T7118	TOYOTA	CAMRY	SV42	1994-1998	SV42. 3SFE. 2WD
T7118	TOYOTA	VISTA	SV30	1990-1994	SV30. 4SFE. 2WD
T7118	TOYOTA	VISTA	SV40	1994-1998	SV40. 4SFE. 2WD
T7118	TOYOTA	VISTA	SV41	1994-1998	SV41. 3SFE. 2WD
T7118	TOYOTA	VISTA	SV42	1994-1998	SV42. 3SFE. 2WD


Contact Supplier send an enquiry to
confirm suitable car

T7118


MASUMA




**Shock absorber
(structure chart)**



**Piston valve assembly
(Schematic diagram)**



**Bottom valve assembly
(Schematic diagram)**



It can restrain the vibration of spring and absorb the energy of road bump influence. It not only affects the riding comfort, but also affects the driving safety, and may cause the damage of other parts if the shock absorber is broken.

The shock absorber is a part need to replace regularly and it's service life is around 80000 km. Even if the shock absorber is not broken, it should be replaced, because the internal part of shock absorber has been worn and tear, it is impossible to judge whether the shock absorber is damaged from the product appearance. To avoid traffic safety issues, replace the shock absorber in time is necessary, and the shock absorbers need to be replaced in pairs to ensure the balance of the vehicle handling and the best driving performance.

How to check if the shock absorber needs to be replaced?

- ① Park the car on a flat road, press both sides manually or press the bumper hard with the foot id open (or press front part of the car), then release hands. If the vehicle stops after rebounds in 2-3 seconds, shock absorber is regarded as to be replacement needed.
- ② When suddenly brake the car at low speed, the car shakes violently, and the human body feels uncomfortable, shock absorber is highly probably broken.
- ③ The car stops after driving about 10km on the road with poor conditions, if you don't feel any temperature even cold by hand touch the housing of shock absorber, that is to say, shock absorber is not working normal due to no resistance internal itself.

SHOCK ABSORBER?

What advantage

1. No noise
2. No oil leakage
3. Durable and easy to control
4. More comfortable and stable





Stable Driving



No Oil Leaking



Anti-shaking



Noise Free



High
Temperature
Endurance



Long Lasting

SHOCK ABSORBER

Are you worried about the quality ?




Abnormal Noise?




oil Leaking?



Turning Bend?



Shock Absorber (structure chart)





Less Noise And More Comfortable !!

Quiet design only for your comfortable experience



Comfortable
driving



Increase braking
distance



Improve stability
and security

Reinstall in Situ Fit Perfectly



Product Details



HARDWARE METAL

High-strength piston rod, strong and wear-resistant



BRAND CODE

MASUMA product code identification



INSTALLATION

It can be replaced directly without any change



MASUMA

Note:

MASUMA auto parts covered more than 900,000 different OEM numbers, [here only show few parts.](#)
Pls Contact us to check more and details information for you.

Search For Car Brand (Click)	Auto parts	Product List	Number of suitable car models
For Japanes Car: For Toyota For Honda For Nissan For Mazda For Lexus For Infiniti For Mitsubishi For Suzuki For Subaru For DAIHATSU For ISUZU For Fuso	Auto Engine Systems	Air Filters	1215
		Fuel Filters	255
		Oil Filters	588
		Spark Plugs	59
		Engine Mounts	888
		Ignition Coils	255
		Ignition Cable	77
		Timing Chain Kit	67

		Cylinder Head Gaskets	223
		Ball Joints	655
For Korean Car:		Control Arms	394
For HYUNDAI		Rubber Bushing	685
For KIA		Shock Absorber Springs	153
		Shock Absorbers	323
For Europe Car:	Auto Suspension Systems	Stabilizer Links	453
For Benz		Suspension Strut	110
For BMW		Bearings	
For Audi		Brake Pads	1966
For VW		Brake Discs	825
For Porsche		Brake shoes	220
For Skoda			
For Renault			
For Peugeot			
For Volvo	Auto Brake Systems	Brake Cables	216
For Alfa Romeo		Brake Hoses	707
		Tie Rod Ends	345
For America Car:		Tie Rods (Rack End)	247
For Ford	Auto Steering Systems	Steering Gear Boots	435
For OPEL		Steering Gears	60
For Chevrolet			
	Air Conditioning Systems	Cabin Filters	736
		C.V. Joints	199
Other brand:		C.V. Joint Boots	157
For Land Rover	Auto Transmission Systems	Tensioner & Belts	1043
For Jeep		Wheel Hubs	103
For Ssangyong		Antifreeze	4
		Brake Lubricants	2
	Fluid & Chemicals	Engine Lubricants	42
		Transmission Fluids	15
		Other Auto Parts	5074
		Tire Repair Tools	57
		Auto Fastener & Clip	1881
	Other Auto Parts	Lug Nuts & Accessories	233
		Other Vehicle Tools	15

MASUMA

MAIN CAR SERIES

Cover 90% Of JAPANESE And KOREA Cars



Corolla



Crown



Camry



Civic



Tiida



Accord



RX300



RAV4



Golf



Passo



HR-V



Fortuner



Yaris



Avanza



Land Cruiser



Pajero(Montero)



Mirage



Stream



Hilux



CR-V



Legacy



Fit (jazz)



HiAce



X-Trail



Primera



Cedric



Mazda 3



Mazda 6



Prius



City



Impreza



Focus



Company Profile



[View more history >>](#)

MASUMA was founded in **1998 Japan**, integrates R&D, production, sales and operation as one. It has its own wholly-owned subsidiary factory and joint venture production base in **GuangZhou China**, have an area of **30,000 sqm**, **500+ employees** in the company, the annual turnover to reach 55 million USD. Masuma specializes in the design, development, manufacturing, sales and service of Japanese, German, American, Chinese and Korean auto parts. The current products include lubricating oil, transmission fluid, brake oil, brake pad, brake disc, filter, spark plug, ignition coil, ball joint, swing arm, shock absorber, belt, wiper, water tank cover and other series, over ten thousands of varieties, and products are sold to more than 100 countries and regions in the world.

MASUMA	1998			1
2011		30,000	500	55
Masuma		100		



Manufacturing Technique



PRECISION

Automated machinery

100,000 pieces/day



TAKAMAZ-FEELER



BROTHER SPEEDIO



TOYO



Mitutoyo QC



NGATA



KAWATA

Exhibition

EXHIBITION



MASUMA Masuma (Guangzhou) International Trading Co., Ltd.

+8615323309608

msm@masuma.com

masumajp.com

No. 19, Liwu Road, Tanbu Town, Huadu District, Guangzhou